



## Errata

# NFPA 1911

## Standard for the Inspection, Maintenance, Testing, and Retirement of In-Service Automotive Fire Apparatus

### 2007 Edition

**Reference:** 22.7.4.2, 22.7.4.3, and 22.7.4.5

**Errata No.:** 1911-07-1

The Committee on Fire Department Apparatus notes the following error in the 2007 edition of NFPA 1911, *Standard for the Inspection, Maintenance, Testing, and Retirement of In-Service Automotive Fire Apparatus*.

*1. Revise text as follows:*

**22.7.4.2** The power source shall be loaded to 50 percent  $\pm$ 10 percent of the load specified in 22.7.2 ~~22.3.2~~, and the voltage and frequency shall be measured and recorded.

**22.7.4.3** The power source shall be loaded to the load specified in 22.7.2 ~~22.3.2~~, and the voltage and frequency shall be measured and recorded.

**22.7.4.5** The power source shall be unloaded to 50 percent  $\pm$ 10 percent of the load specified in 22.7.2 ~~22.3.2~~, and the voltage and frequency shall be measured and recorded.

**Issue Date:** February 21, 2008