



Errata

NFPA 79

Electrical Standard for Industrial Machinery

2007 Edition

Reference: 6.3.1

Errata No.: 79-07-3

The Committee on Electrical Equipment of Industrial Machinery notes the following error in the 2007 edition of NFPA 79, *Electrical Standard for Industrial Machinery*.

6.3.1 General. Protection against indirect contact (*see 3.3.18*~~19.2~~) is intended to prevent hazardous conditions to continue in the event of a fault condition (e.g., insulation failure between live and exposed conductive parts).

Issue Date: April 13, 2009

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)